M5 Update



Follow These Instructions As They Are In Order

- First go to our Website
 - o <u>www.eGPS.net</u>
 - Please find the SUPPORT Tab, the choose "Help Center"
- Select the M5 GNSS Receiver tab
 - Find Updating Your M5
 - You will need to download the following files:

NOTE: These Files Are For the M5 GNSS Receiver Only

- Updating Your M5 | PDF
- update_GNSS_v21893_43_b20220121 | BIN
- update_M5_v1.2.1_b20211222 | BIN
- Turn on eGPS M5 GPS unit, ensure battery life is full or at least 70%
- Connect
 - o Select internet access from your toolbar
 - GPS unit will show up as GNSS-(Serial number)
 - And Connect
- GPS IP Address
 - o http://192.168.1.1
 - If you cannot see this webpage, you are not connected.
 - o Login
 - User: admin
 - Password: password
 - Choose firmware on the bottom-left of the page
 - Choose Firmware Update
 - Click Browse
 - You will use file update_M5_v1.2.1_b20211222
- Connect to GPS, Enter GPS IP address again, and go back to the firmware selection
 - Choose GNSS Board Upgrade
 - Click Browse and select file update_GNSS_v21893_43_b20220121
 - This will take about 20 minutes to complete.
 - Login back in to make sure everything is updated.
 - Go back to firmware section
 - Firmware version for main board should be 1.2.1
 - Hardware version for GPS board should be 5.43